


Soldering Components

焊接

Step1 Solder components on the base board from 1 to 4 marked in the following picture.

步骤1

按编号由小到大的 顺序对各电子元件 依次进行焊接。



① Vibration sensor 振动传感器 Fold the pin to 90 degree and attach the sensor on the front. Solder the tube on the front side, then solder the pin on the

back. Finally, cut off the extra pin. 细管脚弯折90°后从正面插入;先把其圆柱外壳焊接到正面的两个焊 盘上,然后在反面相应焊盘处焊接细管脚,最后剪掉多余管脚。

Soldering Components

② Resistor 电阳

Fold the pins to 90 degree and attach the component on the front. Then solder the pins on the back side and cut off the extra pins. 管脚弯折90度后从正面插入,在反面相应焊盘处

焊接,最后剪掉多余管脚。



③ Battery holder 电池座 Attach it on the front, then solder its pins on the back.

从正面插入,在反面相应焊盘处焊接。

④ LED (Orange) 橙色LED灯

Attach it on the front, then solder its pins on the back. Finally, cut off the extra pins .

从正面插入, 在反面相应焊盘处焊接, 最后剪掉多余管




Soldering Components

Insert batteries

The LED will flash when hit or shaked strongly.






Components

Solder the flashing LED

Soldering

on the pillar A

步骤3 将快闪LEI 焊接在支柱A上。



Soldering Components 焊接

Step4

Insert pillar B to pillar A to form a bracket with a crossing stand. Then place this bracket on the base and solder them together. Make sure the positive plates has been connected, as showed in the following.

8 0 0

www.DFRobot.com

Made in China

Designed by Designed by

dfrobot


将支柱A和支柱B十字交叉后, 焊接到底板上。

步骤4

Shuttlecock 组装

Step1 Put all the components together as the picture showed from bottom to top.

> 步骤1 如图, 组装底座部分。



Shuttlecock

Assembling

Step2 Insert feathers.

> 步骤2 如图, 插入羽毛。



配件清单

Parts List

x1 PCB Base Board PCB-底座

x1 PCB Pillar A

PCB-支柱A PCB-支柱B

x1 PCB Pillar B

x1 Vibration Sensor 振动传感器

x1 Flashing LEI

碳膜电阻100欧

金属膜电阻1M欧

直插3mm橙色LED

直插3mm七彩快闪LED

硅胶管

背胶毛毡垫

x2 Battery CR1220 电池CR1220

x2 Battery holder 电池座